



01 Mar 2006

Lessons Learned from the St. Francis Dam Failure

J. David Rogers

Missouri University of Science and Technology, rogersda@mst.edu

Follow this and additional works at: https://scholarsmine.mst.edu/geosci_geo_peteng_facwork



Part of the [Geology Commons](#)

Recommended Citation

J. D. Rogers, "Lessons Learned from the St. Francis Dam Failure," *Geo-Strata*, vol. 6, no. 2, pp. 14-17, American Society of Civil Engineers (ASCE), Mar 2006.

This Article - Journal is brought to you for free and open access by Scholars' Mine. It has been accepted for inclusion in Geosciences and Geological and Petroleum Engineering Faculty Research & Creative Works by an authorized administrator of Scholars' Mine. This work is protected by U. S. Copyright Law. Unauthorized use including reproduction for redistribution requires the permission of the copyright holder. For more information, please contact scholarsmine@mst.edu.



March/April 2006

Geo-Institute
10th Anniversary
Year

Geo-Strata

Lessons Learned from Fantastic Failures



***** CR-LOT 0001A#C-000

J David Rogers

00005

Dept Of Geological Engineering

00082

University Of Missouri Rolla

129 McNutt Hall 1870 Miner Cr

Rolla MO 65409-0001

Features

Lessons Learned from the St. Francis Dam Failure	14
<i>By J. David Rogers, Ph.D., P.E., P.G., M.ASCE</i>	
The 1953 Dike Failures in the Netherlands.....	18
<i>By Herman Gerritsen</i>	
The Vajont (Vaiont) Landslide.....	27
<i>By David N. Petley, Ph.D.</i>	
Large Landslide Risks in Solid Waste Facilities—	32
Geotechnical Fundamentals Count	
<i>By David M. Hendron, P.E.</i>	
10th Anniversary of the Geo-Institute	35
<i>By N. Catherine Bazán-Arias, Ph.D., P.E.</i>	

Columns

President's Letter	4
Letters to the Editor	6
From the Editorial Board.....	10
Commentary: The Value of Hindsight.....	12
<i>By Ralph B. Peck, P.E., Hon. Member, ASCE</i>	
GeoCurmudgeon	38
CoreBits	40

How to submit information to *Geo-Strata* magazine.

To submit letters to the editor, comments, industry news, G-I member information, allied organization information or abstracts for articles to be considered for future *Geo-Strata* editions, please submit in Word format (do not send PDF's) and e-mail them to: geo-strata@asce.org. Photos must be sent as a separate jpeg or tif format file. Contact lbayer@asce.org for additional information.

As it is the objective of GEO-STRATA to be a forum for the free expression and interchange of ideas, the opinions and positions stated in signed material are those of the authors, and not by the fact of publication, necessarily those of the American Society of Civil Engineers or the Geo-Institute. Contributing authors are requested and expected to disclose any financial, economic, or professional interests or affiliations that may have influenced positions taken or advocated in their articles. Editorial guidelines may be obtained upon request from the Editor. GEO-STRATA is published bi-monthly by the American Society of Civil Engineers, 1801 Alexander Bell Drive, Reston, VA 20191-4400. Application to mail at periodicals postage rates is pending at Herndon, VA and at additional mailing offices. POSTMASTER: Send address changes to GEO-STRATA, the Geo-Institute of ASCE, 1801 Alexander Bell Drive, Reston, VA 20191-4400.

Copyright © 2006, American Society of Civil Engineers, PRINTED IN THE U.S.A.

All Rights Reserved.



Editorial Board

Jim Withiam, Ph.D.

D'Appolonia
412.856.9440
jlwithiam@dappolonia.com

N. Catherine Bazán-Arias, Ph.D., P.E.

GAI Consultants
412.476.2000
n.bazan-arias@gaiconsultants.com

Jeff Dunn, Ph.D., P.E., G.E.

Kleinfelder, Inc.
925.484.1700
jdunn@kleinfelder.com

David A. Pezza, P.E.

U.S. Army Corps of Engineers
202.761.4831
david.a.pezza@hq02.usace.army.mil

Jerry Samford, P.G.

Virginia Geotechnical Services, P.C.
804.266.2199
wjsamford@vgspc.com

Andy Steele, P.E.

Steele Foundations, Inc.
202.342.1194
Andy@SteeleFoundationsInc.com

Publisher

Robert Silverstein

703.295.6234
rsilverstein@asce.org

2005-2006 G-I Board of Governors

Stephen G. Wright, Ph.D., P.E. President
John Anderson, Ph.D., Vice-President
Arthur Hoffmann, P.E., Treasurer
Jean-Louis Briaud, Ph.D., P.E.
Jerry A. DiMaggio, P.E.
Ed Kavazanjian, Ph.D., P.E.
Stein Sture, Ph.D.
Carol Bowers,* P.G., Secretary

*ex-officio, nonvoting member

G-I Staff

Carol W. Bowers, P.G.

Director
703.295.6352
cbowers@asce.org

Linda R. Bayer Manager and Production

703.295.6162
lbayer@asce.org

Amy Dearborn Program Coordinator

703.295.6313
adearborn@asce.org

Kristie C. Kehoe Content Coordinator

703.768.8046
writingpro@cox.net

Geo-Institute Website

www.geoinstitute.org

Advertising Sales Managers

Sheri Fuller

410-584-8485

Charles Minor

847-854-1666

Richard Railton

909-587-2982

Jeff Sandersen

703-295-6107

Lessons Learned from the St. Francis Dam Failure

By J. David Rogers, Ph.D., P.E., P.G., M.A.S.C.E.

The St. Francis Dam (Figure 1), a curved concrete gravity structure 209-feet high, located in the mountains about 35 miles north of downtown Los Angeles, failed catastrophically near midnight just before March 12, 1928. The failure released 36,180 acre-feet of water down San Francisquito Canyon on a turbulent 55-mile journey to the Pacific Ocean near Ventura, killing 450 people. As the deadliest American civil engineering failure of the 20th century, the city of Los Angeles paid more than \$7 million in restitution to the victims' families and affected landowners. The sudden failure of a new concrete dam constructed by a reputable public agency had enormous repercussions within the civil engineering profession, especially in California.

The city of Los Angeles and its chief water engineer, William Mulholland, came to national prominence between 1906-13 with the construction of the 237-mile long Los Angeles-Owens River Aqueduct, the longest water conveyance system ever conceived until that time. Designed to provide 258 mgd, the city suffered water shortages in the early 1920s because of a regional drought. Mulholland devised a 5-year plan to increase municipal storage by 67,000 ac-ft in Los Angeles by constructing eight new dams. He had already built 22 hydraulic fill earth dams, but his last two dams were mass concrete because their mountainous sites were devoid of sufficient clay or water to construct hydraulic fills.

The St. Francis site was wonderful from a topographic perspective, lying just below a broad, tree-filled glen in the Sierra Pelona between the San Gabriel and San Andreas faults. The linear canyon was structurally controlled by the ancient San Francisquito Fault, juxtaposing pre-Cambrian Pelona Schist against Oligocene Vasquez formation (then called the Sespe fm), an arkosic sandstone and conglomerate. Mulholland's subordinates designed the two concrete dams using the methods then in use—which ignored formal considerations of hydraulic uplift beneath the dam and assumed the concrete to be impermeable. (These assumptions were proven erroneous in the years following the St. Francis failure.) The city's concrete dam designs were relatively crude, in that they lacked grout curtains, grouted contraction joints, internal drains, or inspection galleries. There also was no engineering geologic input regarding the suitability of the foundations or abutments for such high structures. The shear key excavated along the upstream heel was only 3 x 3 feet deep, and the sloping abutments were not provided with stepped shear keys.



Figure 1. St. Francis Dam was a curved concrete gravity arch structure 209 feet high, constructed between April 1924 and May 1926 (W.L. Huber Collection, U.C. Water Resources Center Archives, Berkeley, colorized by P. Horton).

Potential Problems

The July 1923 plans specified a 500-ft radius of curvature for the main structure, rising 175 feet high above the streambed with a maximum base width of 141 ft, sufficient to store 30,000 ac-ft of water, which equaled the amount consumed by Los Angeles' citizens in 1922-23. Shortly before construction began in April 1924, the reservoir capacity was increased to 32,000 ac-ft, so the dam was raised 10 feet, without increasing the base width. In July 1925, the dam was raised an additional 10 feet because of Los Angeles' meteoric growth—now to a capacity of 38,000 ac-ft, but again without increasing the base width.


The dam was completed in May 1926, using 130,500 yds³ of concrete with an average compressive strength (fc') between 1760 and 2430 psi. The city began filling the reservoir on March 1, 1926, but it was not filled to capacity until just five days before the failure, in March 1928. On the day of the failure (March 12th), Mulholland personally inspected the dam along with his assistant chief engineer, Harvey Nan Norman. They observed nothing to register alarm, yet twelve hours later the dam failed.

Why the Failure Occurred

The dam failed catastrophically just before midnight on March 12, 1928, killing nearly 450 people. A dozen panels were appointed to investigate the failure by various agencies and interested parties. They pointed to the dam's inadequate foundation as the culprit—specifically, the tendency of the Vaqueros formation to slake profusely upon saturation, and alleged hydraulic piping of this material along the San Francis-




Figure 2. Ground view looking upstream at remains of the St. Francis Dam after its untimely failure in March 1928. Note the dramatic fault contrast between the Vasquez conglomerate at extreme left with the silvery Pelona Schist. The San Francisquito fault pierced the dam's right abutment and was blamed for the dam's collapse (C.H. Lee Collection, U.C. Water Resources Center Archives, Berkeley, colorized by P. Horton).



GEONOR, INC.
 109 Greenwood Circle
 (P.O. Box 903)
 Milford, PA 18337
 Tel: 1-570-296-4884
 Fax: 1-570-296-4886
 geonor@geonor.com
 www.geonor.com

GEOTECHNICAL INSTRUMENTATION APPLICATION ENGINEERING

- ✓ Instruments
- ✓ Cabling
- ✓ Data Acquisition



Consoil
 Hydrostatic
 Profiler




H-10
 100' (30m) depth

ASTM/ISO
 Standard

Field Vane Shear Test Equipment

H-60 Hand-held
 Vane -10' (3m) depth



H-70
 30' (10m) depth

quito fault, about halfway up the right abutment (Figure 2). The most cited investigation was that of the commission appointed by California Governor C.C. Young, comprised of four engineers and two geologists. The commission convened in Los Angeles on March 19—a week after the failure. They spent one day at the dam site, two days reviewing documents, and two days writing its report, which was released on March 27.

Subsequent studies I have made suggest that the dam's untimely demise was more complex than originally thought, involving the partial reactivation of an ancient bedrock landslide which comprised the dam's entire left abutment. A Stevens Water Stage Recorder on the dam's surviving central block (Figure 3) recorded a slight drawdown of the reservoir pool from 8:00 pm onward, which dropped with increasing severity during the last 40 minutes of the record. The 1928 investigations assumed the gage recorded simple outflow, but post-failure images show a massive tension crack at the dam's upstream heel, containing the gage attendant's wooden access ladder (Figure 3). This suggests that the dam's heel was in tension and tilting downstream when the dam failed. After the failure, Mulholland testified that the factor of safety against overturning "was in excess of 4," but the repeated heightening of the dam without commensurate increases in the base width created a dangerous situation. A simple check of full

reservoir pressure inside the heel crack shows that the overturning factor of safety would have been reduced to 0.77! The Stevens Gage actually recorded a half degree of cantilever tilt, which I confirmed using a 2D finite element model.

Southern California Edison County's 70 KV Lancaster power line ran along San Francisquito Canyon, past the dam. It was destroyed at 11:57-1/2 pm where it crossed the dam's left abutment 40 ft above the dam crest. Physical evidence suggests that the entire left abutment detached itself as a massive landslide carrying a portion of the dam on 700,000 yd³ of schist (Figure 4). This formed a temporary landslide dam which the outpouring reservoir quickly enlarged, reaching a peak outflow of about 1.7 million cfs.

Lessons Learned

Mulholland subsequently faced criminal prosecution by the Los Angeles County District Attorney, and willingly accepted responsibility for the disaster, stating: "Don't blame anyone else. Whatever fault there was on the job, put it on me. If there were any errors in judgment—and it's human to make mistakes—the error was mine." When all of the forensic investigations were completed, the most often-cited conclusion about St. Francis came from the Los Angeles County Coroner's Inquest, which addressed the need for peer review of any criti-

Cone Penetrometer Testing

Full line of Environmental and Geotechnical Testing Capabilities:

- ✓ Piezo-CPT
- ✓ Seismic-CPT
- ✓ Hydrocarbon Detection
- ✓ Video-CPT
- ✓ VOC Detection
- ✓ Soil Moisture / Resistivity
- ✓ Gamma Radiation Detection
- ✓ Soil, Gas, and Water Sampling



**APPLIED
RESEARCH
ASSOCIATES, INC.**

1-800-639-6315

1-802-763-8348

www.cpt.ara.com

Aiken SC - Richland WA - Houston TX - So. Royalton VT




Figure 3. Upstream face of the remaining portion of St. Francis Dam, after the failure. The broken Stevens Gage can be seen near the crest, bent towards the left abutment, indicating out-rushing water flow in that direction. A prominent crack up the upstream heel is seen at lower right hand side (C.H. Lee Collection, U.C. Water Resources Center Archives, Berkeley, colorized by P. Horton).

cal structure. It stated: "A sound policy of public safety and business and engineering judgment demands that the construction and operation of a great dam should never be left to the sole judgment of one man, no matter how eminent, without ... checking by independent experts." Heeding this admonition, California's state engineer (which later became the Division of Safety of Dams—the nation's preeminent dam safety agency) was given review powers over all non-federal dams.

The St. Francis Dam failure also affected the Boulder Canyon Project which was then on the verge of being approved by Congress in 1928. The Boulder Dam project called for a massive curved concrete gravity arch dam 700 feet high which was being promoted by southern California water interests, including Mulholland. Two months after St. Francis failed, Congress named an independent

panel, headed by retired Corps of Engineers General William Siebert, to review the Bureau of Reclamation's design of Boulder Dam. The panel ended up selecting the Black Canyon site, ordered the flood storage increased to 9.5 million ac-ft by increasing the dam height another 25 ft (to 730 ft), increased the foundation bearing pressure to 40 tsf, and ordered channel diversion and spillway capacities increased by another 35 percent. Shortly after their findings were released, the \$165 million Boulder Canyon Project—the largest federally-funded project in history at that time (December 1928)—was approved by Congress,

The following year in 1929, California enacted professional registration for civil engineers. The St. Francis tragedy also drew attention to the importance of engineering geologic input in site selection, which became standard practice, as did engineering geology in the civil engineering curriculum. A vigorous debate erupted about the development of hydraulic uplift beneath dams, which continued into the early 1950s. The destabilizing impacts of hydraulic uplift on steep-sided abutments was not fully appreciated until after the Malpasset Dam failure in December 1959. The failure took years to unravel.

The three-dimensional complexity of blocky dam foundations under seepage forces continues to evolve. The siting of dams against landslides was not specific to St. Francis. In fact, since Rogers' first article appeared in 1992, Schuster (in press) has compiled a list of 254 American dams greater than 35-ft high, most of which were unknowingly constructed against old landslides. Many of these are being re-evaluated in light of these recent revelations. ○

J. David Rogers, Ph.D., P.E., P.G., M. A.S.C.E., holds the Karl F. Hasselmann Missouri Chair in Geological Engineering at the University of Missouri-Rolla. He can be reached at rogersda@umr.edu.



Figure 4. Aerial oblique view of the St. Francis Dam failure taken the following morning, looking upstream. The left abutment landslide is clearly visible, extending almost 200 feet above the reservoir pool elevation (Spense Aerial Photo Collection, UCLA Geography Department).