

Jacek F. Gieras
Rong-Jie Wang
Maarten J. Kamper

Axial Flux Permanent Magnet Brushless Machines

Second Edition

 Springer

Contents

1	Introduction	1
1.1	Scope	1
1.2	Features	1
1.3	Development of AFPM Machines	3
1.4	Types of Axial Flux PM Machines	3
1.5	Topologies and Geometries	6
1.6	Rotor Dynamics	10
1.7	Axial Magnetic Field Excited by PMs	12
1.8	PM Eddy-Current Brake as the Simplest AFPM Brushless Machine	14
1.9	AFPM Machines versus RFPM Machines	17
1.10	Power Limitation of AFPM Machines	19
	Numerical Examples	19
2	Principles of AFPM Machines	29
2.1	Magnetic Circuits	29
2.1.1	Single-Sided Machines	29
2.1.2	Double-Sided Machines With Internal PM Disc Rotor	29
2.1.3	Double-Sided Machines With Internal Ring-Shaped Core Stator	31
2.1.4	Double-Sided Machines With Internal Slotted Stator ..	33
2.1.5	Double-Sided Machines With Internal Coreless Stator ..	33
2.1.6	Multidisc Machines	34
2.2	Windings	35
2.2.1	Three-Phase Windings Distributed in Slots	35
2.2.2	Toroidal Winding	36
2.2.3	Coreless Stator Winding	36
2.2.4	Non-Overlap (Concentrated Coil) Windings	38
2.3	Torque Production	40
2.4	Magnetic Flux	42

2.5	Electromagnetic Torque and EMF	43
2.6	Losses and Efficiency	45
2.6.1	Stator Winding Losses	45
2.6.2	Stator Core Losses	46
2.6.3	Core Loss Finite Element Model	48
2.6.4	Losses in Permanent Magnets	48
2.6.5	Rotor Core Losses	49
2.6.6	Eddy Current Losses in Stator Conductors	50
2.6.7	Rotational Losses	51
2.6.8	Losses for Nonsinusoidal Current	52
2.6.9	Efficiency	53
2.7	Phasor Diagrams	53
2.8	Sizing Equations	56
2.9	Armature Reaction	58
2.10	AFPM Motor	62
2.10.1	Sine-Wave Motor	62
2.10.2	Square-Wave Motor	63
2.11	AFPM Synchronous Generator	66
2.11.1	Performance Characteristics of a Stand Alone Generator	66
2.11.2	Synchronization With Utility Grid	67
	Numerical Examples	68
3	Materials and Fabrication	79
3.1	Stator Cores	79
3.1.1	Nonoriented Electrical Steels	79
3.1.2	Amorphous Ferromagnetic Alloys	82
3.1.3	Soft Magnetic Powder Composites	84
3.1.4	Fabrication of Stator Cores	84
3.2	Rotor Magnetic Circuits	88
3.2.1	PM Materials	89
3.2.2	Characteristics of PM Materials	94
3.2.3	Operating Diagram	99
3.2.4	Permeances for Main and Leakage Fluxes	102
3.2.5	Calculation of Magnetic Circuits With PMs	105
3.2.6	Fabrication of Rotor Magnetic Circuits	107
3.3	Windings	109
3.3.1	Conductors	109
3.3.2	Fabrication of Slotted Windings	110
3.3.3	Fabrication of Coreless Windings	111
	Numerical Examples	112

4	AFPM Machines With Iron Cores	123
4.1	Geometries	123
4.2	Commercial AFPM Machines With Stator Ferromagnetic Cores	124
4.3	Some Features of Iron-Cored AFPM Machines	125
4.4	Magnetic Flux Density Distribution in the Air Gap	126
4.5	Calculation of Reactances	128
	4.5.1 Synchronous and Armature Reaction Reactances	128
	4.5.2 Stator Leakage Reactance	128
4.6	Performance Characteristics	132
4.7	Performance Calculation	132
	4.7.1 Sine-Wave AFPM Machine	132
	4.7.2 Synchronous Generator	135
	4.7.3 Square-Wave AFPM Machine	137
4.8	Finite Element Calculations	138
	Numerical Examples	140
5	AFPM Machines Without Stator Cores	153
5.1	Advantages and Disadvantages	153
5.2	Commercial Coreless Stator AFPM Machines	153
5.3	Coreless Stator AFPM Microgenerators	155
5.4	Performance Calculation	155
	5.4.1 Steady-State Performance	155
	5.4.2 Dynamic Performance	158
5.5	Calculation of Coreless Winding Inductances	160
	5.5.1 Classical Approach	160
	5.5.2 FEM Approach	161
5.6	Performance Characteristics	165
5.7	Performance of Coreless Non-Overlap Winding AFPM Machines	166
5.8	Eddy Current Losses in the Stator Windings	170
	5.8.1 Eddy Current Loss Resistance	170
	5.8.2 Reduction of Eddy Current Losses	172
	5.8.3 Reduction of Circulating Current Losses	174
	5.8.4 Measurement of Eddy Current Losses	175
5.9	Armature Reaction	175
5.10	Mechanical Design Features	179
	5.10.1 Mechanical Strength Analysis	179
	5.10.2 Imbalanced Axial Force on the Stator	183
5.11	Thermal Problems	183
	Numerical Examples	184

6	AFPM Machines Without Stator and Rotor Cores	193
6.1	Advantages and Disadvantages	193
6.2	Topology and Construction	193
6.3	Air Gap Magnetic Flux Density	195
6.4	Electromagnetic Torque and EMF	198
6.5	Commercial Coreless AFPM Motors	198
6.6	Case Study: Low-Speed AFPM Coreless Brushless Motor	200
6.6.1	Performance Characteristics	200
6.6.2	Cost Analysis	202
6.6.3	Comparison With Cylindrical Motor With Laminated Stator and Rotor Cores	203
6.7	Case Study: Low-Speed Coreless AFPM Brushless Generator	205
6.8	Characteristics of Coreless AFPM Machines	206
	Numerical Examples	208
7	Control	217
7.1	Control of Trapezoidal AFPM Machine	217
7.1.1	Voltage Equations	218
7.1.2	Solid-State Converter	220
7.1.3	Current Control	223
7.1.4	Speed Control	225
7.1.5	High Speed Operation	226
7.2	Control of Sinusoidal AFPM Machine	227
7.2.1	Mathematical Model and dq Equivalent Circuits	227
7.2.2	Current Control	233
7.2.3	Speed Control	233
7.2.4	Hardware of Sinusoidal AFPM Machine Drive	237
7.3	Sensorless Position Control	241
	Numerical Examples	242
8	Cooling and Heat Transfer	251
8.1	Importance of Thermal Analysis	251
8.2	Heat Transfer Modes	251
8.2.1	Conduction	252
8.2.2	Radiation	252
8.2.3	Convection	253
8.3	Cooling of AFPM Machines	256
8.3.1	AFPM Machines With Self-Ventilation	257
8.3.2	AFPM Machines With External Ventilation	265
8.4	Lumped Parameter Thermal Model	269
8.4.1	Thermal Equivalent Circuit	269
8.4.2	Conservation of Energy	271
8.5	Machine Duties	272
8.5.1	Continuous Duty	272

8.5.2	Short-Time Duty	272
8.5.3	Intermittent Duty	273
	Numerical Examples	274
9	Applications	281
9.1	Power Generation	281
9.1.1	High Speed Generators	281
9.1.2	Low Speed Generators	284
9.2	Electric Vehicles	286
9.2.1	Hybrid Electric Vehicles	287
9.2.2	Battery Electric Vehicles	291
9.2.3	Fuel Cell Electric Vehicles	294
9.3	Ship Propulsion	295
9.3.1	Large AFPM Motors	295
9.3.2	Propulsion of Unmanned Submarines	297
9.3.3	Counterrotating Rotor Marine Propulsion System	297
9.4	Electromagnetic Aircraft Launch System	299
9.5	Mobile Drill Rigs	301
9.6	Oil Beam Pumps	302
9.7	Elevators	305
9.8	Miniature AFPM Brushless Motors	308
9.9	Vibration Motors	310
9.10	Computer Hard Disc Drives	312
9.11	Ventricular Assist Devices	313
9.12	Axial Flux Machines with Superconducting Field Excitation System	317
	Numerical Examples	322
	Symbols and Abbreviations	327
	References	335
	Patents	351
	Index	357