

Neutrons and Synchrotron Radiation in Engineering Materials Science

From Fundamentals to Material and
Component Characterization

Edited by

*Walter Reimers, Anke Rita Pyzalla,
Andreas Schreyer, and Helmut Clemens*



WILEY-VCH Verlag GmbH & Co. KGaA

Contents

Preface XVII

List of Contributors XXI

Part I General 1

1 Microstructure and Properties of Engineering Materials 3

Helmut Clemens and Christina Scheu

- 1.1 Introduction 3
- 1.2 Microstructure 5
 - 1.2.1 Crystal Defects 8
 - 1.2.2 Grain (Phase) Boundaries and Twins 8
 - 1.2.3 Precipitates and Dispersions 9
- 1.3 Microstructure and Properties 12
- 1.4 Microstructural Characterization 15
 - References* 20

2 Internal Stresses in Engineering Materials 21

Anke Rita Pyzalla

- 2.1 Definition 21
 - 2.1.1 Stress Tensor, Strain Tensor, and Elasticity Tensor 21
 - 2.1.1.1 Stress Tensor 21
 - 2.1.1.2 Strain Tensor 22
 - 2.1.2 Definitions, Residual Stresses 24
 - 2.1.2.1 Stress Equilibrium 24
 - 2.1.2.2 Residual Macro- and Microstresses 25
- 2.2 Origin of Residual Macro- and Microstresses 27
 - 2.2.1 Residual Stress Formation in Primary Forming Processes 29
 - 2.2.2 Residual Stress Formation in Heat Treatment Processes 30
 - 2.2.2.1 Residual Stresses in a Material without Phase Transformation (Pure Cooling Residual Stresses) 30

2.2.2.2	Residual Stresses in a Material with Phase Transformation	31
2.2.2.3	Residual Stress Formation in Surface Hardening Processes (Nitriding, Carbo-Nitriding, and Case Hardening)	33
2.2.3	Residual Stress Formation in Forming Processes	34
2.2.3.1	Deep-Rolling Residual Stresses	35
2.2.3.2	Cold Extrusion Residual Stresses	37
2.2.4	Residual Stress Formation in Metal Cutting Manufacturing	39
2.2.4.1	Grinding Residual Stresses	40
2.2.5	Residual Stress Formation in Joining Processes	42
2.2.6	Residual Stress Formation in Coatings	46
2.3	Relevance	48
2.3.1	Failure due to Residual Stress Formation or Residual Stress Relief Induced by Temperature Changes	49
2.3.2	Influence of Residual Stresses on Component Failure Under Static and Dynamic Mechanical Loads	50
2.3.3	Influence of Residual Stresses on Component Failure in Corrosive Environments	53
2.3.4	Influence of Residual Stresses on Wear	53
	<i>References</i>	55
3	Texture and Texture Analysis in Engineering Materials	57
	<i>Heinz-Günter Brokmeier and Sang-Bong Yi</i>	
3.1	Introduction	57
3.2	Pole Figures	60
3.3	Texture Measurements on Laboratory Scale	62
3.3.1	X-ray Diffraction	62
3.3.2	Electron Diffraction	63
3.4	Texture Measurements at Large-Scale Facilities	65
3.4.1	Neutron Diffraction	65
3.4.1.1	Texture of Semifinished Products	68
3.4.2	Texture Analysis Using Synchrotron X-rays	70
3.4.2.1	Local Texture Measurement in an Extruded Mg Rod	73
3.4.2.2	Global Texture in Cu Wire	74
3.4.2.3	<i>In situ</i> Texture Measurement at Elevated Temperatures	74
3.4.2.4	<i>In situ</i> Texture Measurement Under Loading	75
	<i>References</i>	76
4	Physical Properties of Photons and Neutrons	79
	<i>Andreas Schreyer</i>	
4.1	Introduction	79
4.2	Interaction of X-Ray Photons and Neutrons with Individual Atoms	80
4.2.1	Neutrons	81
4.2.2	X-Rays	83

4.3	Scattering of X-Ray Photons and Neutrons from Ensembles of Atoms	86
	<i>References</i>	89
5	Radiation Sources	91
5.1	Generation and Properties of Neutrons	91
	<i>Wolfgang Knop, Philipp Klaus Pranzas, and Peter Schreiner</i>	
5.1.1	Introduction	91
5.1.2	Generation of Neutrons	91
5.1.2.1	Research Reactors	91
5.1.2.2	Spallation Sources	93
5.1.3	Instrumentation	96
	<i>References</i>	97
5.2	Production and Properties of Synchrotron Radiation	97
	<i>Rolf Treusch</i>	
5.2.1	Introduction	97
5.2.2	Properties of Synchrotron Radiation	100
5.2.3	Sources of Synchrotron Radiation	105
5.2.3.1	Bending Magnets	106
5.2.3.2	Wigglers and Undulators	107
5.2.4	Outlook: Free Electron Lasers	109
5.2.5	Summary	111
	<i>References</i>	112
Part II	Methods	113
6	Introduction to Diffraction Methods for Internal Stress Analyses	115
	<i>Walter Reimers</i>	
6.1	General Aspects	115
6.2	Principles of Diffraction Methods	116
6.3	Principles of Strain Determination by Diffraction Methods	118
6.4	Determination of the Stress-Free Interplanar Lattice Distance d_0	121
6.5	$\sin^2 \psi$ -Technique	122
6.6	Nonlinear Lattice Strain Distributions	123
6.6.1	Anisotropy	123
6.6.2	Strain/Stress Gradients	125
6.6.3	Shear Strains/Stresses	127
6.7	Diffraction Elastic Constants	128
6.7.1	Calculation of DEC	129
6.7.2	Experimental Determination of the DEC	129

6.8	Experimental Set-up and Measuring Procedures	130
6.8.1	Experimental Set-up	130
6.8.1.1	Diffractionmeters	130
6.8.1.2	Diaphragms	132
6.8.1.3	Detectors	132
6.8.2	Measuring Procedures	132
6.9	Overview on In-depth and Local Residual Stress Analysis	133
	<i>References</i>	134
7	Stress Analysis by Angle-Dispersive Neutron Diffraction	137
	<i>Peter Staron</i>	
7.1	Introduction	137
7.2	Diffractionmeter for Residual Stress Analysis	138
7.2.1	Set-up of a Diffractionmeter for Strain Scanning	138
7.2.2	Monochromator	139
7.2.3	Slit System	140
7.2.4	Sample Positioning	141
7.2.5	Detector	141
7.3	Measurement and Data Analysis	142
7.3.1	Gauge Volume and Sample Positioning	142
7.3.2	Data Reduction and Analysis	144
7.3.2.1	Data Reduction and Peak Fitting	144
7.3.2.2	Calculation of Stresses	145
7.3.2.3	Macro and Microstresses	147
7.3.2.4	Stress-Free Reference	147
7.4	Examples	148
7.4.1	Residual Stresses in Friction Stir Welded Aluminum Sheets	148
7.4.2	Residual Stresses in Water-Quenched Turbine Discs	150
7.5	Summary and Outlook	152
	<i>References</i>	152
8	Stress Analysis by Energy-Dispersive Neutron Diffraction	155
	<i>Javier Roberto Santisteban</i>	
8.1	Introduction	155
8.2	Time-of-Flight Neutron Diffraction	155
8.2.1	TOF Peak Shape and Data Analysis Packages	157
8.3	TOF Strain Scanners	159
8.3.1	Counting Times and Resolution	160
8.3.2	Neutron Optics and Time Focusing	163
8.4	A Virtual Laboratory for Strain Scanning	164
8.5	Evolution of Intergranular Stresses	168
8.6	TOF Transmission Analysis	170
8.6.1	Bragg Edges	171

- 8.6.2 Strain Mapping 172
- 8.6.3 Quantitative Phase Analysis 172
- 8.6.4 Other Applications 174
- 8.7 Conclusions 174
- References 175*

- 9 Residual Stress Analysis by Monochromatic High-Energy X-rays 177**
René Valéry Martins
- 9.1 Basic Set-ups 177
- 9.2 Principle of Slit Imaging and Data Reconstruction 180
- 9.3 The Conical Slit 181
- 9.3.1 Working Principle 181
- 9.3.2 Capabilities 182
- 9.3.3 Example 183
- 9.4 The Spiral Slit 184
- 9.4.1 Functional Principle 184
- 9.4.2 Capabilities 186
- 9.4.3 Example 186
- 9.5 Simultaneous Strain Measurements in Individual Bulk Grains 188
- 9.6 Coarse Grain Effects 189
- 9.7 Analysis of Diffraction Data from Area Detectors 191
- 9.8 Matrix for Comparison and Decision Taking Which Technique to Use for a Specific Problem 193
- References 193*

- 10 Residual Stress Analysis by White High Energy X-Rays 195**
- 10.1 Reflection Mode 195**
Christoph Genzel
- 10.1.1 Motivation 195
- 10.1.2 Basic Relations in Depth-Resolved Energy-Dispersive X-Ray Stress Analysis (XSA) in Reflection Geometry 196
- 10.1.3 Experimental Set-up 199
- 10.1.4 Example for Depth-Resolved Residual Stress Analysis by ED Diffraction 200
- 10.1.5 Concluding Remarks and Prospects 205
- References 206*

10.2	Transmission Mode	207
	<i>Anke Rita Pyzalla</i>	
10.2.1	Motivation	207
10.2.2	Experiment Set-up and Experimental Details	208
10.2.2.1	Penetration Depth	208
10.2.2.2	Gauge Volume and Spatial Resolution	209
10.2.2.3	Example for an Experiment Set-up	211
10.2.3	Data Evaluation	213
10.2.4	Examples	214
10.2.5	Conclusions	218
	<i>References</i>	218
11	Diffraction Imaging for Microstructure Analysis	221
	<i>Thomas Wroblewski</i>	
11.1	Introduction, the Principle of Diffraction Imaging	221
11.2	The MAXIM Experiment at HASYLAB Beamline G3	222
11.3	Data Structure	223
11.4	Strategies for Data Reduction and Visualization	224
11.5	Outlook, Bulk Imaging	226
	<i>References</i>	228
12	Basics of Small-Angle Scattering Methods	229
	<i>Philipp Klaus Pranzas</i>	
12.1	Common Features of a SAS Instrument	229
12.2	Contrast	230
12.3	Scattering Curve	230
12.4	Power Law/Scattering by Fractal Systems	232
12.5	Guinier and Porod Approximations	233
12.6	Macroscopic Differential Scattering Cross Section	234
12.7	Model Calculation of Size Distributions	235
12.8	Magnetic Structures	236
	<i>References</i>	237
13	Small-Angle Neutron Scattering	239
	<i>Philipp Klaus Pranzas</i>	
13.1	Nanocrystalline Magnesium Hydride for the Reversible Storage of Hydrogen	240
13.2	Precipitates in Steel	242
13.3	SiO ₂ Nanoparticles in a Polymer Matrix – an Industrial Application	245
13.4	Green Surfactants	246
	<i>References</i>	248

- 14 Decomposition Kinetics in Copper–Cobalt Alloy Systems: Applications of Small-Angle X-ray Scattering** 249
Günter Goerigk
- 14.1 Introduction 249
- 14.2 ASAXS Fundamentals 249
- 14.3 Results of ASAXS Experiments Characterizing the Decomposition in Copper–Cobalt Alloys 252
- 14.4 Outlook 255
- 14.5 Summary 255
References 256
- 15 B3 Imaging** 257
Wolfgang Treimer
- 15.1 Radiography 257
- 15.1.1 Fundamentals 257
- 15.1.2 Interactions of Neutrons with Matter 259
- 15.1.3 Geometries 261
- 15.1.4 Resolution Functions 264
- 15.1.5 Image Degradation 267
- 15.1.6 Other Imaging Techniques 269
- 15.2 Tomography 274
- 15.2.1 Mathematical Introduction 274
- 15.2.2 Slice Theorem, Shannon Theorem 276
- 15.2.3 Image Reconstruction 277
- 15.3 New Developments in Neutron Tomography 281
References 285
- 16 Neutron and Synchrotron-Radiation-Based Imaging for Applications in Materials Science – From Macro- to Nanotomography** 287
Felix Beckmann
- 16.1 Introduction 287
- 16.1.1 Attenuation-Contrast Projections 287
- 16.1.2 Phase-Contrast Projections 288
- 16.1.3 Phase-Enhanced Projections 289
- 16.1.4 Direct Phase-Contrast Projections 289
- 16.1.5 Indirect Phase-Contrast Projections 290
- 16.2 Parallel-Beam Tomography 290
- 16.2.1 Measurement and Reconstruction 291
- 16.2.2 Density Resolution and Detector Quality 292
- 16.2.3 Data Evaluation and Visualization 295
- 16.3 Macrotomography Using Neutrons 296
- 16.3.1 Experimental Set-up 296

- 16.3.2 Measurements and Results 297
- 16.4 Microtomography Using Synchrotron Radiation 300
 - 16.4.1 Beamline Optics 300
 - 16.4.2 Experimental Set-up 301
- 16.5 Summary and Outlook 306
 - References* 306

- 17 μ -Tomography of Engineering Materials 309**
 - Astrid Haibel*

 - 17.1 Advantages of Synchrotron Tomography 309
 - 17.2 Applications and 3D Image Analysis 310
 - 17.2.1 Discharging Processes in Alkaline Cells 310
 - 17.2.2 Microstructural Investigations of Nb₃Sn Multifilamentary Superconductor Wires 312
 - 17.2.3 Influence of the Foaming Agent on Metallic Foam Structures 314
 - 17.3 Image Artifacts 316
 - 17.3.1 Ring Artifacts 316
 - 17.3.2 Image Noise 317
 - 17.3.3 Edge Artifacts 318
 - 17.3.4 Motion Artifacts 318
 - 17.3.5 Centering Errors of the Rotation Axis 319
 - References* 320

- 18 Diffraction Enhanced Imaging 323**
 - Michael Lohmann*

 - 18.1 Introduction 324
 - 18.1.1 Basics 324
 - 18.1.2 Extinction Contrast 325
 - 18.1.3 Principles of DEI 326
 - 18.2 Experimental Set-up 328
 - 18.3 Examples 329
 - 18.3.1 Complete Set of DEI Images 329
 - 18.3.2 Material Science 329
 - 18.3.3 Example of Mineralogical Investigations 331
 - 18.4 Conclusions 332
 - References* 332

Part III New and Emerging Methods 333**19 3D X-ray Diffraction Microscope 335***Henning Friis Poulsen, Wolfgang Ludwig, and Søren Schmidt*

- 19.1 Basic Set-up and Strategy 336
 - 19.1.1 The 3DXRD Microscope 338
- 19.2 Indexing and Characterization of Average Properties of Each Grain 339
 - 19.2.1 Application I: Nucleation and Growth Studies 340
 - 19.2.2 Application II: Plastic Deformation 341
 - 19.2.3 Application III: Studies of Subgrains and Nanocrystalline Materials 342
- 19.3 Mapping of Grains and Orientations 343
 - 19.3.1 Mode III: Mapping Grains in Undeformed Specimens 343
 - 19.3.2 Mode IV: Mapping Orientations in Deformed Specimens 345
 - 19.3.3 Application I: Recrystallization 346
 - 19.3.4 Application II: Grain Growth 347
- 19.4 Combining 3DXRD and Tomography 348
 - 19.4.1 Grain Mapping by Tomography 349
- 19.5 Outlook 350
 - References* 350

20 3D Micron-Resolution Laue Diffraction 353*Gene E. Ice*

- 20.1 Introduction 353
 - 20.1.1 The Need for *Polychromatic* Microdiffraction 353
- 20.2 Theoretical Basis for Advanced Polychromatic Microdiffraction 355
 - 20.2.1 Modified Ewald's Sphere Description of Laue Diffraction 355
 - 20.2.2 Qualitative Information: Phase, Texture, Elastic Strain, Dislocation Density 356
 - 20.2.2.1 Phase 356
 - 20.2.2.2 Texture 357
 - 20.2.2.3 Dislocation Tensor 357
 - 20.2.2.4 Elastic Strain Tensor 357
- 20.3 Technical Developments for an Automated 3D Probe 357
 - 20.3.1 Source 358
 - 20.3.2 Microbeam Monochromator 359
 - 20.3.3 Nondispersive Focusing Optics 361
 - 20.3.4 Area Detector 361
 - 20.3.5 Differential Aperture 361
 - 20.3.6 Software 362

20.4	Research Examples	363
20.4.1	3D Grain Boundary Networks	363
20.4.2	Deformation Behavior and Grain Boundaries	364
20.4.3	Deformation in Single Crystals	365
20.4.4	Grain Growth on Surfaces and in Three-Dimensions	366
20.4.5	Anomalous Grain Growth	367
20.5	Future Prospects and Opportunities	369
	<i>References</i>	370
21	Quantitative Analysis of Three-Dimensional Plastic Strain Fields Using Markers and X-ray Absorption Tomography	371
	<i>Kristoffer Haldrup and John A. Wert[†]</i>	
21.1	Introduction	371
21.2	Experimental Approach	372
21.2.1	Markers	372
21.2.2	Particle Tracking and DGT Calculation	372
21.2.3	Spatial Resolution	373
21.3	Results of Investigations	373
21.3.1	Homogeneous Deformation	373
21.3.2	Heterogenous Deformation	374
21.3.3	Microstructural Effects	375
21.4	Outlook	376
	<i>References</i>	377
22	Combined Diffraction and Tomography	379
	<i>Anke Rita Pyzalla and Augusta Isaac</i>	
22.1	Introduction	379
22.2	Experimental Set-up	380
22.3	Example: Combined Diffraction and Tomography for Investigating Creep Damage Evolution	381
22.3.1	Scientific Background	381
22.3.2	Experimental Details	381
22.3.2.1	Miniature Creep Device	381
22.3.2.2	Tomography and Diffraction	381
22.3.2.3	Material	382
22.3.3	Results	382
22.4	Conclusions and Outlook	385
	<i>References</i>	386

Part IV Industrial Applications 387**23 Diffraction-Based Residual Stress Analysis Applied to Problems in the Aircraft Industry 389***Peter Staron, Funda S. Bayraktar, Mustafa Koçak, Andreas Schreyer, Ulrike Cihak, Helmut Clemens, and Martin Stockinger*

- 23.1 Motivation 389
- 23.2 Residual Stresses in Turbine Disks 390
 - 23.2.1 Introduction 390
 - 23.2.2 Material 391
 - 23.2.3 Finite Element Modeling 393
 - 23.2.4 Neutron Diffraction 395
 - 23.2.5 Results 396
 - 23.2.5.1 *In Situ* Tensile Test 396
 - 23.2.5.2 Stresses in a Turbine Disk 397
 - 23.2.5.3 Stresses in a Thin Plate 398
 - 23.2.6 Summary 400
- 23.3 Residual Stresses in Laser-Welded Al Joints 400
 - 23.3.1 Introduction 400
 - 23.3.2 Materials and Welding 401
 - 23.3.3 Neutron Diffraction 404
 - 23.3.4 Stresses in Laser-Welded T-Joints 405
 - 23.3.5 Stresses in Laser-Welded Butt Joints 407
 - 23.3.6 Summary 408
- 23.4 Conclusions 409
 - References* 410

24 Optimization of Residual Stresses in Crankshafts 413*Anke Rita Pyzalla*

- 24.1 Introduction 413
- 24.2 Experimental Determination of Residual Stresses in Crankshafts 414
- 24.3 Experimental Results and Implications 416
- 24.4 Conclusions 418
 - References* 419

Index 421