
Weldability of ferritic steels

NORMAN BAILEY

BMet. CEng. FIM. FWeldI

ABINGTON PUBLISHING

Woodhead Publishing Ltd in association with The Welding Institute

Cambridge England

Contents

<i>Introduction</i>	viii
<i>Acknowledgements</i>	xi
1 Factors influencing weldability	1
The welding process	1
Steel types	3
Weld cooling cycle	9
The heat-affected zone	14
The weld metal	18
Cutting and gouging	28
Residual stresses	29
Post-weld heat treatment	32
Weldability formulae	35
References	43
2 Potential welding problem areas	45
Cracking	45
Welding faults	45
Inspection for defects	46
Joint integrity	46
Problems associated with PWHT	46
Service problems	47
Repair	47
Joining dissimilar steels	47
Joining dissimilar metals	50
References	53
3 Solidification cracking	54
Description	54
Role of composition	66

Solidification cracking and the welding process	74
Control and avoidance of cracking	80
Liquation cracking	86
Copper pick-up	91
Ductility dip cracking	93
Detection and identification	93
References	101
4 Lamellar tearing	102
Description	102
Role of inclusions	104
Susceptible joint types	109
Other factors	115
Control and avoidance of cracking	118
Control tests	119
Detection and identification	128
References	132
5 Hydrogen cracking	133
Description	133
Hydrogen	134
Susceptibility to embrittlement	140
Stress to give cracking	144
Temperature of embrittlement	145
Techniques for avoiding cracking	146
Weld metal hydrogen cracking	155
Detection and identification	159
Other aspects of hydrogen in ferritic steels	162
References	168
6 Reheat cracking	170
Description	170
Role of composition	172
Other influences	173
Control techniques	174
Detection and identification	178
References	179
7 Faults of welding	180
Faults of shape	180
Inclusions	183
Cavities	185
References	186

8	Inspection for defects	187
	Inspection techniques	188
	Inspectability	188
	Consequences of metallurgical features	189
	References	190
9	Joint integrity	191
	Strength and ductility	191
	Toughness	193
	Hardness	204
	Creep resistance	204
	Corrosion resistance	205
	References	209
10	Service problems	210
	Fatigue and corrosion fatigue	210
	Corrosion	211
	Stress corrosion	211
	Loss of toughness in service	212
	High temperature service problems	218
	Graphitisation	220
	References	222
11	Repair	224
	Analysis prior to repair	224
	Limitation of preheat	228
	Need for post-weld heat treatment	228
	Special circumstances	230
	References	235
	<i>Further reading</i>	236
	<i>Glossary</i>	238
	<i>Index</i>	271