

CRYSTAL GROWTH FOR BEGINNERS

Fundamentals of Nucleation, Crystal Growth and Epitaxy

Ivan V Markov

*Bulgarian Academy of Sciences
Sofia, Bulgaria*



World Scientific

Singapore • New Jersey • London • Hong Kong

CONTENTS

Preface	v
1. CRYSTAL-AMBIENT PHASE EQUILIBRIUM	1
1.1. Equilibrium of Infinitely Large Phases	1
1.2. Supersaturation	4
1.3. Equilibrium of Finite Phases	7
1.3.1. Equation of Laplace	7
1.3.2. Equation of Thomson-Gibbs	8
1.4. Equilibrium Shape of Crystals	10
1.4.1. Theorem of Gibbs-Curie-Wulff	13
1.4.2. Polar diagram of the surface energy	17
1.4.3. Herring's formula	20
1.4.4. Stability of crystal surfaces	26
1.5. Atomistic Views on Crystal Growth	32
1.5.1. Equilibrium of infinitely large crystal with the ambient phase — The concept of half-crystal position	32
1.5.2. Equilibrium finite crystal-ambient phase—The concept of mean separation work	35
1.5.3. Equilibrium 2D crystal-ambient phase	37
1.5.4. Equilibrium shape of crystals—Atomistic approach	38
1.5.5. Equilibrium vapor pressure of a 2D crystal on a foreign substrate	40
1.6. Equilibrium Structure of Crystal Surfaces	41
1.6.1. Classification of crystal surfaces	41
1.6.2. Equilibrium structure of a step	44
1.6.3. Equilibrium structure of F faces	48
1.6.3.1. Model of Jackson	50
1.6.3.2. Model of Temkin	53

1.6.3.3. Criterion of Fisher and Weeks	58
1.6.4. Kinetic roughness	62
2. NUCLEATION	63
2.1. Thermodynamics	63
2.1.1. Homogeneous formation of nuclei	65
2.1.2. Heterogeneous formation of 3D nuclei	69
2.1.3. Heterogeneous formation of elastically strained 3D nuclei	75
2.1.4. Formation of 2D nuclei	81
2.1.5. Mode of nucleation on a foreign substrate	83
2.2. Rate of Nucleation	86
2.2.1. General formulation	86
2.2.2. The equilibrium state	89
2.2.3. Steady state nucleation rate	92
2.2.4. Nucleation of liquids from vapors	95
2.2.5. Statistical contributions	97
2.2.6. Nucleation from solutions and melts	98
2.2.7. Rate of heterogeneous nucleation	103
2.2.8. Rate of 2D nucleation	106
2.2.8.1. Rate of 2D nucleation from vapors	106
2.2.8.2. Rate of 2D nucleation from solutions	106
2.2.8.3. Rate of 2D nucleation in melts	107
2.2.9. Atomistic theory of nucleation	108
2.2.10. Nonsteady state nucleation	118
2.2.11. Saturation nucleus density	128
2.2.12. Ostwald's step rule	139
3. CRYSTAL GROWTH	147
3.1. Normal Growth of Rough Crystal Faces	148
3.2. Layer Growth of Flat Faces	155
3.2.1. Rate of advance of steps	157
3.2.1.1. Growth from vapor phase	157
3.2.1.2. Growth from solutions	170
3.2.1.3. Growth from melts	177
3.2.2. Spiral growth of F faces	179
3.2.2.1. Shape of the growth spiral	179
3.2.2.2. Growth from a vapor phase	185
3.2.2.3. Growth in solutions	190
3.2.2.4. Growth in melts	192

3.2.3. Growth by 2D nucleation	192
3.2.3.1. Constant rates of nucleation and step advance	193
3.2.3.2. Time-dependent rates of nucleation and step advance	201
3.2.4. Influence of surface anisotropy—Growth of Si(001) vicinal surface	222
3.2.4.1. Dimer's structure	224
3.2.4.2. Structure and energy of steps	226
3.2.4.3. Ground state of vicinal Si(100) surfaces	234
3.2.4.4. Anisotropy of surface diffusion coefficient	237
3.2.4.5. Theory of 1D nucleation	239
3.2.4.6. Rate of step advance by 1D nucleation	245
3.2.4.7. Growth of Si(001) vicinal by step flow	246
3.3. Kinematic Theory of Crystal Growth	250
3.4. A Classical Experiment in Crystal Growth	261
4. EPITAXIAL GROWTH	281
4.1. Basic Concepts and Definitions	281
4.2. Structure and Energy of Epitaxial Interfaces	288
4.2.1. Boundary region	288
4.2.2. Models of epitaxial interfaces	289
4.2.3. Misfit dislocations	292
4.2.4. Frank–van der Merwe model of thin overlayer	295
4.2.4.1. Interatomic potentials	295
4.2.4.2. Interfacial interactions	300
4.2.4.3. 1D model of epitaxial interface	301
4.2.4.4. 2D model of Frank and van der Merwe	319
4.2.4.5. Comparison of 2D and 1D models	325
4.2.4.6. Application of 1D model to thickening overlayer	326
4.2.4.7. 1D model with non-Hookean interatomic forces	329
4.2.4.7.1. Effect of anharmonicity in epitaxial interfaces	329
4.2.4.7.2. Influence of nonconvexity in epitaxial interfaces	336
4.2.5. van der Merwe model of thick overgrowth	359
4.2.6. Thickening overgrowth	366
4.2.7. The Volterra approach	371
4.3. Mechanism of Growth of Thin Epitaxial Films	375

4.3.1. Relation of Dupré for misfitting crystals	386
4.3.2. Thickness dependence of chemical potential	388
4.3.3. Thermodynamic criterion for modes of growth	392
4.3.4. Kinetics of growth of thin epitaxial films	393
4.3.5. Critical temperature for transition from 2D to 3D growth	399
4.3.6. Cross hatch patterns	405
References	406