Practical Gamma-Ray Spectrometry

GORDON GILMORE

Nuclear Training Services, Warrington, UK

JOHN D. HEMINGWAY

Nuclear Training Services, Warrington, UK and Department of Physics, University of Liverpool, Liverpool, UK

JOHN WILEY & SONS

Chichester · New York · Brisbane · Toronto · Singapore

Contents

Preface			vii
1	Radioactiv	ve Decay and the Origin of Gamma- and X-Radiation	1
2	Interactio	ns of Gamma-Radiation with Matter	22
3	Semicond	luctor Detectors for Gamma-Ray Spectrometry	38
4			62
5	5 Statistics of Counting		104
6	Spectrom	eter Calibration	128
7	True Coin	ncidence Summing	148
8	Compute	r Analysis of Gamma-Ray Spectra	160
9	Scintillati	on Spectrometry	183
10	0 Choosing, Setting up and Checking the Specification of a Detector		199
11	Resolutio	n: Origins and Control	216
12	Troublesh	nooting	225
13	Low Cou	nt Rate Systems	237
14	High Cou	int Rate Systems	259
15	Ensuring	Quality in Gamma-Ray Spectrometry	272
Ap	pendix A	Sources of Information	29 1
Ap	pendix B	Gamma-Ray and X-Ray Standards for Detector Calibration	294
Ap	pendix C	Gamma-Ray Energies in the Detector Background and the Environment,	
		Including those seen Following the Chernobyl Reactor Accident	300
Appendix D		Chemical Names and Symbols	304
Appendix E		Manufacturers and Suppliers Mentioned in the Text	307
Ind	dex		309